

HALLBERG RASSY 352.



TECHNICAL DATA

Length	10,54	Width	3,38
Draft	1,63	Displacement	6700
Year of construction	1980	Year of registration	1980
Maximum speed	7	Cruising speed	5,5
Flag		VAT	Vat paid
Category	Brokerage		

PRICE	euro 62.000
	+5% commission

"Data deemed correct, but not contractual. This does not constitute, in any case, a contractual document."

HALLBERG RASSY 352.

DESCRIPTION

Good general conditions, good condition of the sails and rigging, many works carried out in 2024, read notes. Engine replaced in 1999 with Volvo Penta MD22L.

FUEL AND ENGINES

N. Tanks	2	Tank material	stainless steel
Tanks capacity	240 Lt	Fuel type	diesel
N. Engine	1	Engine Manufacturer	volvo penta
Engine model	md22l bt	Engine power	51
Engine hours	1700	Transmission	shaft line

CONSTRUCTION MATERIAL

Hull	fiberglass
Coachroof	fiberglass
Deck	fiberglass

WATER SYSTEM

N. Tanks	1	Tanks capacity	300 Lt
Tanks material	fiberglass	Water pump	yes
Watermaker	no	Water heater	yes

ELETTRICAL SYSTEM

Voltage	12-220v	Battery charger	yes
N. Battery	3	Battery capacity	250 Ah
Generator	no	Make	
Inverter	yes		

INTERIOR DESCRIPTION

- Double cabin forward
- Double cabin aft
- Spacious living room with 2 sofa/bad
- kitchenette
- Toilet room

HALLBERG RASSY 352.

DESCRIPTION OF ARMAMENTS

Storm sail	N. 2 Jib (no Furling)	N. 1 Furling Genoa Light
N. 1 Full Batten main sail with Ronstan traveller	Rigid wang	Wind generator
2 Solar panels	Staysail stay	Furlex furling Jib
2 Selftail winch 46.2 speed	2 winch	n. 2 folding table inside/outside
Fridge	Tv System + LCD TV	1.2 kW inverter
Battery charger	2 service + 1 Engine	Battery monitor
HI-FI external speakers	Webasto	3 gas Burners + oven
Teak Cockpit	2 Sprayhood (new one and old one)	Bimini Top

ELETTRONICS INSTRUMENTATION

Compass	2 GPS Raymarine	Depth sounder
Raymarine VHF	Raymarine autopilot	Raymarine wind station
Furuno weather station	AIS transmitter + receiver with display and alarm functionality	

ADDITIONAL NOTES

Works 2024: Transom painting Engine disembarkation for timing belt replacement, cleaning of the heat exchanger, and complete service, oil seal replacement, rust cleaning and painting. Cutlass bearing replacement Rubber stuffing box replacement 220V electrical system replacement 12V electrical system overhaul Valve engine water intake and through-hull replacement WC valve overhaul Replacing the black water tank valve Navigation lights replacement Hull blue line renewed Steering rudder leather cover replacement Bathroom ladder reinforcements The water tank float replaced Engine and service battery replacement TV antenna replacement

HALLBERG RASSY 352.



HALLBERG RASSY 352.



HALLBERG RASSY 352.



HALLBERG RASSY 352.



HALLBERG RASSY 352.



HALLBERG RASSY 352.



HALLBERG RASSY 352.



HALLBERG RASSY 352.



HALLBERG RASSY 352.



HALLBERG RASSY 352.



HALLBERG RASSY 352.



HALLBERG RASSY 352.



HALLBERG RASSY 352.



HALLBERG RASSY 352.



HALLBERG RASSY 352.



HALLBERG RASSY 352.



HALLBERG RASSY 352.



HALLBERG RASSY 352.



HALLBERG RASSY 352.



HALLBERG RASSY 352.




HALLBERG RASSY 352.



HALLBERG RASSY 352.



HALLBERG RASSY 352.



HALLBERG RASSY 352.



HALLBERG RASSY 352.



HALLBERG RASSY 352.



HALLBERG RASSY 352.



HALLBERG RASSY 352.

